



## Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



**Daily Update**  
July 13

### Repair Work

Devil's Slide (post mile 39.14)

- Level 'B' (lower level ocean side) – Drilling for tie backs was completed today. 58 of 58 tie backs now installed. Tie back stressing continued.
- Level 'D' (upper level cliff side) – Drilling for tie backs continued today from the bench. 29 of 33 now installed. Cable stressing started today.



Drilling at level D



Cable stressing – level D

### Retaining (micropile) Wall

- Drilling and driving steel piles continued today. 45 of 99 now installed.



Micropile drilling



View of installed micropiles.

### Rock Bolts Above The Road

- Drilling continued today to install 50 rock bolts above the level D bracing wall.